
Chiller sensor −2 K
Chiller sensor −1 K
Chiller sensor +1 K
Chiller sensor +2 K
DP sensor −20 %
DP sensor −10 %
DP sensor +10 %
DP sensor +20 %
Tower sensor −2 K
Tower sensor −1 K
Tower sensor +1 K
Tower sensor +2 K
Tower fouling 95 % UA
Tower fouling 80 % UA
Tower fouling 65 % UA
Chiller fouling 95 % UA
Chiller fouling 65 % UA
Tower PI tuning
Bypass leak 25 %
Bypass leak 50 %
Bypass leak 75 %
Bypass stuck 50 %
Bypass stuck 75 %
1
10
20
30
40
52
Week of the year
1
6
12
18
23
Priority rank (1: repair first)