


Assembling missing emergency pulling.


Edition Date: 13/03/17 Edition: Piotr Miechoński

Assembling of missing emergency pulling support can be fixed on already installed landing doors. To make easier please loosen or unscrew panel from the carriage.




It will be easier to increse distance betwen mechanism base and carriage arm - pull a little bit arm to put nut

behing the carriage arm.



	Qty	Denomination	Reference
1	1	Emergency pulling	TC000219
2	2	Bolt M6x16 mm	DIN 933
3	4	Contact washer Ø6,1 mm	NF E25- 511-M
4	2	Nut M6	DIN 6923

All necessery parts will be delivered on warranty free of costs. Please follow the pictures below:







TYPE OF DOCUMENT CODE

Document title

Version:



Additinal drawing of assambled carraige.

