

P5 SOLDER CLEARANCE - SINGLE COPY

J1 power; J2 Rload; J3 Q1 Vbe; J4 Q2 Vbe. Pin1 + / pin2 -.

Top-coordinate review only; mask orientation is unconfirmed.