Details

Dworkin WiFi Survey Result

Business Centre 2071 Regus Rinvägen Ringvägen 100E, 9tr Stockholm Sweden

Report Date 2019-06-07

Version: 1

Survey Completed By: Per Orest

Time Spent on Site: 2,00

No. of Access Point/s Installed: 8

Brand/Model of Access Point/s:

A. Description of the issues (customer's

feedback).

B. Survey Details + Settings Netspot +

Export options

C. Installed Access Point Locations (AP

Floor Map)

D. Photo of Installed Access Point/s

E. Map Results

F. Current AP connections in the

Comms Room

G. Conclusion/Recommendation Reinstal

Reinstall APs and upgrade all to the same level

Low speed and bad connections on WiFi

Edit | Back to List