

Aurelia Grand Hotel Group

Maintenance Escalation Manual

Room defect priority, repair documentation, room blocking, and engineering escalation standards

Document ID	AGHG-MNT-004
Owner	Engineering and Property Operations
Version	3.0
Effective Date	04 Jul 2026
Review Cycle	Semiannual or after major operational incident
Classification	Confidential - Internal Hotel Operations
Applies To	Engineering, rooms division, front office, and property leadership
Approved By	Chief Engineer, Group Operations

Purpose and usage

This controlled document defines operational standards for hotel teams. It is intended to support consistent decisions, clear accountability, accurate record keeping, and high-quality service recovery across Aurelia properties. Teams must apply local legal requirements when those requirements are stricter than this standard.

Contents

Maintenance Priority Levels

Room Blocking and Release Rules

Common Guest-Impact Defects

Repeat Defect Escalation

Work Order Documentation Standards

Coordination with Front Office and Housekeeping

Vendor, Parts, and Preventive Maintenance Controls

Safety and Security Repair Controls

Engineering Shift Handoff Template

System-Specific Troubleshooting Standards

Spare Parts, Temporary Equipment, and Room Sale Decisions

Engineering Incident Summary Template

1. Maintenance Priority Levels

Maintenance prioritization balances guest safety, room usability, revenue protection, and staff capacity. The priority level assigned in the work order must match the guest impact and operational risk, not merely the convenience of the repair.

Priority	Definition	Response target	Examples
P1 - Safety critical	Immediate risk to guest, staff, property, or security.	Immediate dispatch; manager notified.	Door lock failure, exposed wiring, flooding, broken glass, fire-life-safety system alert.
P2 - Guest comfort critical	Room function materially affects sleep, hygiene, privacy, or temperature.	Same shift; room move or block if unresolved.	AC not cooling, no hot water, blocked toilet, major noise from equipment.
P3 - Service impairment	Issue affects convenience but room remains usable.	24 hours where possible.	TV issue, slow drain, minor furniture defect, lamp out.
P4 - Planned maintenance	Cosmetic or preventive task with no immediate guest impact.	Scheduled by engineering plan.	Paint touch-up, furniture scuff, preventive filter replacement.

Priority changes

Priority must be raised when the guest is in-house, the issue repeats, the same room has recent related tickets, the guest is moved because of the defect, or the defect appears in a complaint case.

2. Room Blocking and Release Rules

Rooms must be blocked when a defect affects safety, security, hygiene, temperature control, bathroom usability, or basic privacy. Selling a room with a known material defect requires duty manager approval and guest disclosure when legally or operationally required.

Condition	Block room?	Release condition
AC or heating not functioning during climate-sensitive conditions.	Yes, unless temporary fix confirmed and guest accepts.	Technician confirms stable operation and supervisor records test.
Door lock, safe-entry, or balcony lock defect.	Yes.	Security-sensitive repair completed and tested.
No hot water or blocked toilet.	Yes.	Plumbing resolved and housekeeping verifies cleanliness.
Minor cosmetic damage.	No, if room remains safe and presentable.	Log planned repair.
Repeat unresolved defect in same room.	Yes for P2 defects.	Chief engineer or delegate reviews before release.

Release testing

- AC/heating must run long enough to confirm cooling or heating trend.
- Plumbing repairs require water flow test and leak check.
- Door and lock repairs require entry test with guest key and master key according to security procedure.
- Room must be returned to clean status after maintenance work.

3. Common Guest-Impact Defects

The following defect guidance supports consistent handling of frequent guest complaints. Engineering notes should be specific enough for front office and guest experience teams to understand what was found and what was corrected.

Defect	Guest impact	Required work order detail
AC not cooling	Sleep disruption, discomfort, possible room move.	Temperature reading, filter status, fault code, repair action, retest result.
Hot water issue	Hygiene and comfort disruption.	Affected fixture, water temperature, duration, central/local cause.
Noise from equipment	Sleep disruption and room usability.	Source, decibel impression if available, time pattern, mitigation.
Wi-Fi or TV issue	Convenience and business travel impact.	Device, room location, network status, reset or replacement.
Plumbing leak	Safety and cleanliness risk.	Location, severity, water damage, room block status.
Pest or odor report	Trust and hygiene concern.	Inspection finding, room block, vendor or deep-clean action.

AC-specific procedure

1. Confirm thermostat setting and mode.

2. Check supply air temperature and room temperature.
3. Inspect filter, airflow, fan operation, and visible fault indicators.
4. Review recent tickets for same room or equipment zone.
5. If unresolved within same shift, recommend room move and block room.
6. Record final temperature trend after repair.

4. Repeat Defect Escalation

Repeat defects create compensation exposure and guest trust risk. Engineering leaders must review recurring issues even when individual tickets appear minor.

Repeat pattern	Required escalation
Two related tickets for same room within 14 days	Chief engineer review and supervisor inspection before room release.
Three related tickets within 30 days	Room block until root cause review is complete.
Guest complaint references known open ticket	Duty manager and guest experience notified.
Same equipment zone affects several rooms	Property leadership brief and preventive plan.
Vendor repair fails twice	Vendor escalation and alternative repair plan.

Root cause categories

- Equipment failure
- Preventive maintenance gap
- Parts unavailable
- Vendor delay
- Incorrect prior diagnosis
- Room released before validation
- Guest misuse or external factor

5. Work Order Documentation Standards

A work order should allow another qualified person to understand the reported problem, inspection performed, action taken, and remaining risk. Vague notes such as “fixed” are not acceptable for guest-impact defects.

Field	Required content
Room or asset	Room number, asset tag, or equipment zone.
Issue description	Guest/staff report in plain language.
Impact	Safety, comfort, hygiene, room usability, revenue, or cosmetic.
Diagnosis	Observed condition and likely cause.
Action taken	Repair, reset, replacement, vendor call, temporary mitigation.
Verification	Test performed, result, and time.
Room status	Open, resolved, blocked, out of service, or planned follow-up.

Photo and attachment use

Photos should be attached for visible damage, leaks, mold-like staining, broken components, and pre/post repair evidence. Photos must not include unnecessary guest personal items where avoidable.

6. Coordination with Front Office and Housekeeping

Engineering decisions affect room assignment and guest communication. Front office and housekeeping must receive clear status updates when a repair affects check-in, room move, or compensation review.

- Notify front office immediately when a room should not be assigned.
- Notify housekeeping when maintenance work creates dust, water, odor, or room reset needs.
- Notify guest experience when a defect is verified after a complaint.
- Document whether the guest was offered a room move, temporary equipment, or other mitigation.
- Use shift handoff notes for any P1 or P2 issue remaining open at shift end.

Temporary mitigations

Portable fans, heaters, dehumidifiers, or temporary amenities may help in limited circumstances but must not be used to hide unresolved material defects. Safety instructions and local rules must be followed.

7. Vendor, Parts, and Preventive Maintenance Controls

Vendor delays and parts availability can create guest-impact failures if not managed visibly. Critical equipment should have preventive plans and spare-parts thresholds suited to property size and climate.

Control	Standard
Critical parts list	Maintained by chief engineer and reviewed quarterly.
Vendor response tracking	Record request time, promised arrival, arrival time, and completion result.
Preventive maintenance schedule	Room and plant equipment inspected according to calendar and risk.
Missed preventive task	Escalate when missed task relates to guest-impact defect.
Capital risk note	Repeated failures requiring replacement should be reported to property leadership.

Monthly engineering review

Engineering leadership must review repeat defects by room, compensation-linked maintenance issues, rooms blocked for more than 24 hours, and equipment zones with rising ticket volume.

8. Safety and Security Repair Controls

Repairs involving locks, electrical systems, balconies, windows, life-safety systems, and water intrusion require heightened control. These defects may not be treated as ordinary maintenance requests when a guest is in-house or due to arrive.

Control area	Required action
Door lock or access control	Test with appropriate keys/cards; document successful entry and privacy function.
Electrical defect	Isolate hazard, notify manager, and prevent room assignment until safe.
Balcony/window security	Block room until lock or opening restriction is verified.
Water intrusion	Protect guest area, inspect slip risk, coordinate housekeeping cleanup.
Fire-life-safety device	Follow property incident protocol and regulatory requirements.

A safety-sensitive repair must include verification notes. If verification cannot be completed, the room must remain blocked or be released only with property leadership approval.

9. Engineering Shift Handoff Template

Handoff field	Required content
Open P1/P2 tickets	Room, issue, guest status, action taken, next step, owner.
Blocked rooms	Reason blocked, expected release condition, department dependencies.
Vendor calls	Vendor name, time requested, promised arrival, pending parts.
Repeat defects	Rooms with two or more related tickets and current plan.
Guest-impact notes	Any case where front office or guest experience is waiting for engineering result.

Handoff notes must be written before the outgoing engineer leaves the property. A verbal handoff is useful but not sufficient for guest-impact issues.

10. System-Specific Troubleshooting Standards

System-specific standards help engineering staff create consistent notes and determine whether a room can remain in service. The steps below summarize the minimum expected diagnostic information for common guest-impact systems.

System	Minimum diagnostic record	Guest-facing risk
HVAC	Set point, room temperature, supply air trend, filter status, fault code, repair action.	Sleep disruption and temperature discomfort.
Plumbing	Affected fixture, water pressure, hot water temperature, leak source, blockage status.	Hygiene, safety, and room usability.

Electrical	Affected circuit or device, hazard isolated, reset/replacement result, safety verification.	Safety, lighting, charging, and guest confidence.
Locks/access	Guest key test, master key test, latch/deadbolt, battery or hardware condition.	Security and privacy risk.
Internet/TV	Device tested, network status, reset or replacement, property-wide impact.	Business travel and leisure convenience.

For any P2 issue, notes must say whether a room move was recommended. If no room move was recommended, the reason must be clear enough for the duty manager to evaluate guest impact.

11. Spare Parts, Temporary Equipment, and Room Sale Decisions

Parts availability affects whether a defect can be corrected before the next arrival. Engineering must identify critical spares and temporary equipment that can protect guest comfort without compromising safety.

Item/control	Standard
Critical spare threshold	Minimum stock set by chief engineer based on property size, climate, and failure history.
Portable equipment	Fans, heaters, or dehumidifiers may be used only when safe and appropriate.
Unavailable parts	Notify duty manager with expected arrival and sale recommendation.
Temporary repair	Record as temporary and schedule permanent fix before room is sold repeatedly.
Room sale decision	Front office may sell only if defect does not materially affect comfort, safety, hygiene, or promised feature.

A temporary repair that becomes the normal state is a control failure. Repeat use of temporary equipment in the same room should trigger a root-cause review and may require the room to be removed from sale.

12. Engineering Incident Summary Template

Field	Required content
Incident title	Short description of the defect and affected area.
Guest impact	Rooms affected, guests affected, duration, and mitigation.
Root cause	Confirmed cause or current best assessment.
Immediate action	Repair, room block, guest move, vendor call, temporary equipment.
Verification	Testing performed and who confirmed completion.
Preventive action	What will prevent recurrence and who owns it.

Incident summaries are required for P1 issues, repeat P2 issues, property-wide service failures, and any maintenance case connected to a high-value guest recovery decision.