


Pareto Analysis



The first 3 Causes cover 64.29% of the Total Defects

Cumulative Percentage Cutoff:			80%
#	Causes	Defects	Cumulative%
1	Prinint issue	4	28.6%
2	Size variation against specification	3	50.0%
3	Gluing & size issue	2	64.3%
4	Packing related	2	78.6%
5	Hotmelt not done in sleeve	1	85.7%
6	Small ink spot	1	92.9%
7	Wrong material dispatch	1	100.0%
8	Packing related		
Insert new rows above this line			