

GUJARAT PRINT PACK PUBLICATION PRIVATE LIMITED

BRCGS PACKAGING (ISSUE 06) - INTERNAL AUDIT NC REPORT

Format No.: F / SYS / 10

Rev No: 01

Date: 01.05.2013

Page No.: 1 Of 1

Report No.	Feb -25/02	Report Date	17/02/2025	Auditor's Name	Kapila barad
Dept. / Area / Function		Site standard		☒ Non-Conformance	☐ Observation
<u>NC FINDING STATEMENT</u> (Mention details of detected / potential problem) Use of temporary modification using thread and cloth noted in Lamination machine				<u>Objective Evidence(s), if any</u>	
				Reference Record(s)	
				Procedure / Flow Chart No.	
				Clause No. 4.7.6	
Auditor's Sign.		Auditee's Sign.:		Planned Closing Date	
<u>ROOT CAUSE(S)</u> (Carryout a Root Cause Analysis in terms of WHY attributing to as follows, Temporary repairs being carried out were not formally recorded. Machine operators were lacking awareness on the practices to be followed for temporary repairs					
Auditee's Sign.				Auditor's Sign for acceptance	
<u>CORRECTION & CORRECTIVE ACTION</u> (<i>Action Taken to Prevent Recurrence</i>) (Mention in detail the actions taken to prevent the recurrence of this detected problem based on the Root Cause Analysis carried out above. Please mention here only those actions which have been taken and found effective after implementing					
Temporary repairs using thread and cloth noted on Lamination machine has been permanently removed. Machine operators, supervisors & HOD of all processing equipment has been made aware of criteria & methodology for temporary engineering requirements.					
Auditee's Sign.: -				Date:	
<u>Follow-up audit:</u> (Verification and effectiveness of action taken)					
<u>CAR CLOSING VERIFICATION</u> Date: - Verified By: - Sign.: -				Actions Found - Satisfactory / Unsatisfactory CAR - Closed / Not Closed	