Evaluation Warning: The document was created with Spire.PDF for Python.

Evaluation Warning: The document was created with Spire.PDF for Python.

PERSONNEL TRACKING

PERSONNEL TRACKING

CEDIVICE TYPE (DECTORATION)



							ERVICE	TYPE (RES	TUKAT	ION)									PROPE	entymestor	ATION
PTS DOC# _ELECTRONIC	FORM VERIFIER L	INE# 1 INITIALS Bn	JOB NUMBER-COMPLETE			LOSS CAUSE		CODE	LOCATION				WEATHER		JOB STATU		CODE VE	EHICLE NAME (TABLE)		
	START DATE	START DAY	101 108 150					FIRE		L00	Site				HUMID	Nev	v 🗌	RETURN	529 PIC	CKUP, SUV OR CAI	R
DOCTR	1/16/24							WATER/FLOOD WIND		D L01				TEMP 10	Ongoin	g Date -		530 VA	N, PASSENGER/C	.ARGO	
PTS ELE(STOP DATE									L02	02				SNOW	Com	p Time -		518 TR	UCK-MOVING/BO	X/BOARD UP
	1/16/24	/16/24 Tuesday Job Address						MOLE	MOLD		L03				RAIN				523 TR	UCK, 3/4 TON PIC	CKUP
crew sнеет# 212 OakbrookCenter								EARTHQUAKE		L04					WINDY	Hole	d (explain why i	n description)	527 TR	UCK, 1 TON 4X4 V	N/LIFTGATE
LAST 3 LETTERS OF JOB NAME-6 DIGIT DATE-LAST 3 #'S OF VERIFIERS JDE OakbrookL									L05]	Othe	r		453 TR	UCK, EXTRACTION	N	
OOK - 11624 - 109 SAFETY TOPIC					TOOL BOX TRAINING				L06	<u> </u>			Ē]	Contact:			N/A NO) VEHICLE		
00	1/ - 1	1024 - 109	Steel toe			COMPLETED?	ן ם נ									Lockbo	x / Other Code	:	FOR RENTAL	L CARS: CLE CODE AND CH	HECK BOX
		PERSONNEL	NAME			4 HOUR CLOC		TOTAL HOURS	z		HOURS	S			SEE GU	IDE SHEET	≥ SEE TABLE			NEL NAME	ILCK BOX
OFFICE	ID#	CLEARLY PRINT YOUR NAME HELPS ENSU		RATE	24 HOUR	START TIME	24 HOUR	CONFIRM HOURS	LOCATION	PHASE	HOURS BY	_00F	TEST	HARNESS	► HOTEL	HOTEL	VEHICLE			TS THE APPROVAL TO A LACK OF SIGNATUR	
OTTICE	ΙΟπ	NO PA		CLASS	START TIME		STOP TIME	BY PERSON	0CA	CODE	-	IALL]	P - FI	1	照 CODE	ROOM #	SHARE CODE	DOCOMENTED IN		LY OR NO PAY	NE WINT NESSET
1		PRINT FIRST <u>THEI</u>	<u>N</u> LAST NAME		TITVIL	STOP TIME	TIIVIL	BY OTHER		TD G		SMAL	PRP	PFP	<u> </u>	- "		SIC	SNATURE-	-END OF SHIF	T VERIFIER
1011	1793109	Brian nork			700	$\begin{bmatrix} 0 \\ 0 \end{bmatrix}$	900	2.00	L00 .	JBC	2.00	N N	ı N I	N	N Na	Na	N 530 RENTAL	-			Bn
2						0		2.00	L00	JBC	2.00	+	+	\dashv			NI/A	-			VERIFIER
1011	707	Pe dro Forero			700	0	900) 2.00 2.0		JBC	N N		1 N	N	N Na	Na N RENTAL					Bn
3	707	Mich col r	nondor		700	0	000	2.00	L00	JBC	2.00	N N	I N	N	N NIO	No	N/A				VERIFIER
1011	707	Michealr	nendez		700	0	900					''			Na Na	Na	RENTAI				Bn
4											\vdash	N N	ı N	N	N		N	-			VERIFIER
5												+	+	\dashv		1	RENTAI	-			VERIFIER
											\vdash	N N	ı N	N	N		N RENTAI	_			
6												NI N	, N	NI NI	N		N				VERIFIER
												IN I	I N	IN	IN		RENTAI				
7												N I	ı N	N	N		N				VERIFIER
0												+	+	_		-	RENTAI	L			VERIFIER
0											\vdash	N	ı N	N	N		N RENTAI	-			VENIFIEN
9												+	+	\dashv		+	L_IKENTAI	-			VERIFIER
											\vdash	N N	1 N	N	N		N RENTAI				
10												N N	I N	N	N		N				VERIFIER
												.,					RENTAI	L			
11												N	ı N	N	N		N	-			VERIFIER
12												+	+	+	_	+	RENTAI	-			VERIFIER
											\vdash	N N	ı N	N	N		N RENTAI	_			
13														N.	N						VERIFIER
												IN I	I N	IN	IN		RENTAI				
14												N I	ı N	N	N		N				VERIFIER
RESPONSIRII	ITY OF APPROVER:	DI FASE COMPLETE ALL REQUESTS RELOW						VERIFY TOTAL HRS			↑VERIFY TOTA	I UDC	Ш		VERIFICA	TION OF PTS DA	TA RENTAI		ER SIGNATURE TC	VERIFY FORM IS COMP	PLETED
RESPONSIBILITY OF APPROVER: PLEASE COMPLETE ALL REQUESTS BELOW STEP 1-PRINT APPROVER NAME STEP 2-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION?								STEP 3-TOTAL HRS	THESE TW	· · · · · · · · · · · · · · · · · · ·						DES THE PTS CO		1		OVER SIGNATURE	
Jordan Hankey IF "N", YOU MUST VERIFY & COMPLETE ALL OUTSTANDING ISSUES INCLUDING TOP SECTION OF FORM							6	SHOULD	MATCH				■WH		WHERE	WHEN			. Harba		
		O ON LOCATION(S) WORKED AND	TOP SECTION OF FORM D PHASE CODE(S), PLEASE D	ESCRIBE W	HAT WORK TH	IE CREW PERF	ORMED						WOR	K DESC:	LWHA1	WHERE	WHY HOW		Jordan	r Hankey	
job c	heck. Uj	op, loaded up pon arrival spo relf's. Did walk	ke to the ma	nage	r remo	ved al	l equip	ome nt,	exce	pt for	r thre	e fa	ıns	, re	eposit	ion tl	he fans	to blov	v und		
								_												_	
FORM VE	RIFIER-PLEASE	CHECK BOX AND ENTER QU	ANTITY FOR A E& PA	GES I CL	UDED WITH	THIS SHEET		NONE		OF PAG	GE			# OF	PAGE 5		RECIEP'	T TRACKING	FORMS		

PAGE 1