Evaluation Warning: The document was created with Spire.PDF for Python.

Evaluation Warning: The document was created with Spire.PDF for Python.

PERSONNEL TRACKING

PERSONNEL TRACKING



SERVICE TYPE (RESTORATION)													in.								
<u></u> 0	FORM VERIFIER LI	RM VERIFIER LINE # 1 INITIALS Am JOB NUMBER-COMPLETE							LOSS CAUSE		CODE LOCATI			ON WEATHER			JOB STATU		CODE \	/EHICLE NAME (TABL	-E)
0 # 0 0 N	START DATE	START DAY	08149		☐ FIRE		L00	Site				HUMID	Nev	v 🗌	RETURN	529 P	PICKUP, SUV OR CAR				
PTS DOC# ELECTRONIC	1/17/24	· · · · · · · · J						WATER/FLOOD		L01					TEMP 19	Ongoin	g Date -		530 V	/AN, PASSENGER/CARGO	)
	STOP DATE	END DAY	Greystar 1401	ate St			WIND		L02					SNOW	Comp Time -			518 т	RUCK-MOVING/BOX/BC	)ARD UF	
- ",	1/17/24	Wednesday	JOB ADDRESS					MOLI	D	L03					RAIN		d (explain why	. ,	523 T	RUCK, 3/4 TON PICKUP	
CREW SHEET# LAST 3 LETTERS OF JOB NAME-6 DIGIT DATE-LAST 3 #'S OF VERIFIERS JDE  1401 S StateSt Chicago IL						EART	HQUAKE	L04					WINDY	Hol	d [[explain why	n description)	527 T	RUCK, 1 TON 4X4 W/LIF	TGATE		
									L05						Othe	r		453 T	RUCK, EXTRACTION		
ES	T _ 1	1724 - 35	SAFETY TOPIC			TOOL BOX TRA		$\overline{\Box}$		L06						Contac	t:		N/A N	NO VEHICLE	
		1/27 33	Pp e			COMPLETED?				ı						Lockbo	x / Other Code	<u>;</u> :	FOR RENTA	AL CARS: HICLE CODE AND CHECK	BOX
		PERSONNE	L NAME			24 HOUR CLOC		TOTAL HOURS	z		HOUR	S			SEE GUI	DE SHEET	≥ SEE TABLE			NNEL NAME	
OFFICE	ID#	CLEARLY PRINT YOUR NAME HELPS ENSU PAID FOR HOURS WORKED. AN ILLEGIBLE		RATE CLASS	24 HOUR	START TIME	24 HOUR	CONFIRM HOURS	0 ,,,	PHASE CODE	HOURS BY PHASE	TOOLS	TEST	RNESS	NAME	HOTEL ROOM	APRE ROO VEHICLE	YOUR SIGNAT	TURE REPRESE	NTS THE APPROVAL TO PAY	YOUR
		NO PA			START TIME		STOP TIME	BY PERSON					P - FI	2 - HARNE 3 DIEM				DOCOMENTED III	IN UNTIN	TELY OR NO PAY	T NESOEI
1		<b>PRINT</b> FIRST <u>THEN</u> LAST NAME			IIIVIE	STOP TIME	THVIL	BY OTHER				SMA	PRP	PFP PER	CODE		<u> </u>	SI	GNATUR	E-END OF SHIFT	VERIFIE
1011	1786035 Alex mo		orales		700	1200	1800	10.50	L00	EME	10.50	N	I N	N N	Na	Na	N 530 RENTA	_			Am
2						1230 1200 1230	1800	10.50	L00	EME	10.50						NI/A	-			VERIFIE
1011	707	Braylin	Lopez		700							N   N	1 N	N N			N RENTA	ı.			Am
3	707	In an 1	042.07		700	1200	1900	10.50	L00	EME	10.50	NI N	ı N	N N	No	Na	N/A				VERIFIE
1011	707	Jo se 1	opez		700	1230	1800					IN I	N IN	IN IN	Na	Na		l .			
1011	707	Roberto V	/a 701167		700	1200	1800	10.50	L00	EME	10.50	N N	ı N	N N	Na	Na	N N/A	_			VERIFIE
1011	707	1000110	vazquez		700	1230	1000						+		114	114	RENTA	L			Am
												N	I N	N N			N RENTA	_			V 2.1111 12
6																					VERIFIE
												N   N	I N	N N			N RENTA	_			
7												NN	J N	N N			N				VERIFIE
												., .	<u> </u>				RENTA	L			
8												N N	1 N	N N			N — —	-			VERIFIE
9													+				RENTA	-			VERIFIE
												N	I N	N N			N RENTA				
10														NI NI							VERIFIE
												IN I	N IN	N N			RENTA	ι			
11												N N	ı N	N N			N —	_			VERIFIE
12													+				RENTA	L			VERIFIE
												N	1 N	N N			N RENTA	_			VEIMIL
13													+								VERIFIE
												N   N	ı N	N N			N RENTA	ī.			
14												N	J N	N N			N				VERIFIE
													' ''				RENTA				
	LITY OF APPROVER: 1 TEP 1-PRINT APPROV	PLEASE COMPLETE ALL REQUESTS BELOW /ER NAME   STEP 2-DID T	THE FORM VERIFIER REVIEW 1	THIS FORM	FOR COMPLET	ION?		TVERIFY TOTAL HRS	O TOTALS	TOTALS STEP 4-PHASE HRS					FION OF PTS DA		APPROV		TO VERIFY FORM IS COMPLETED  ROVER SIGNATURE		
IF "N". YOU MUST VERIFY & COMPLETE ALL OUTSTANDING ISSUES							42	SHOULD M		40			■who	□ v	VHERE	HERE WHEN			u Hauban		
Jordan Hankey    INCLUDING TOP SECTION OF FORM   100													n grankey								
									1 0	^						1	1.1	11 .			
		id a moisture ch													•		-		-		
we d	id a moist	ure check on th	e wall and four	nd tha	it the le	evels we	ere dro	pping It	shou	ld be	drie d	in c	ne	or t	wo me	ore d	ays and	we can	pull t	he	
equir	ment. W	e extracted more	e water in the	stairw	ell and	disco v	er they	had an	other	leak	in the	sa r	ne	stair	we 11 1	ast n	ight whic	h cause	d the	lobby ce il	ing
equipment. We extracted more water in the stairwell and discover they had another leak in the same stairwell last night which caused the lobby ceiling drywall to start hanging. We removed that section of drywall and set up lay flat into the cavity. They also found leaking where the main generator was														_							
_		king on top of th			•		-	. •			•	•	,				•		_		J
1		-	_		_															•	
able	io cneck	unit 415 for mois	sture level and	ioun	u tnem	to be 11	i ine lo	W ZUS O	ne mo	ore a	ay and	1 W	e si	1 oul	u be a	able 1	o remov	e equipi	me nt.		
FORM VI	RIFIFR-PI FASF	CHECK BOX AND ENTER QU	IANTITY FΩR Δ	MGFSI (1	UDFD WITH	THIS SHEET	Г	NONE		OF PA	GE	1		# OF P	AGE 5	$\neg$	DECIES	T TRACKING	EODMC		
I OINIVI VI	.MI ILIN FILMJE	CHECK DON AND LIVILIN QU	ANTITIONA LA PA	OLDI CL	ODED WITH	TING STILL	L			OI FA	~- <u> </u>	1	Ш	l"			L KECIE⊦	I IKACKING	LOKINI2		

PAGE 1 SIMPSON 052317