Evaluation Warning: The document was created with Spire.PDF for Python. Evaluation Warning: The document was created with Spire.PDF for Python. PERSONNEL TRACKING PERSONNEL TRACKING



SERVICE TYPE (RESTORATION) C) FORM VERIFIER LINE # 1 INITIALS GG JOB NUMBER-COMPLETE LOSS CAUSE CODE LOCATION WEATHER JOB STATUS CODE VEHICLE NAME (TABLE)														RATION							
<u></u>	FORM VERIFIER LINE # 1 INITIALS $_{ m GG}$ JOB NUMBER-COMPLETE 101108503							LOSS CAUSE			LOCATION			W	EATHER	NI	JOB STATUS New RETURN			/EHICLE NAME	: (TABLE)
PTS DOC# ELECTRONIC	START DATE	START DAY	J85U3			FIRE		L00	Job site			_	HUMID		_	RETURN	529 P	PICKUP, SUV OR C	CAR		
DOC CTROI	9/6/24	Friday JOB NAME						WATE	L01					TEMP 70	Ongoing Date -			530 V	/AN, PASSENGER/	/CARGO	
PTS ELEC	STOP DATE	Citizen M Chicago Downtown Hotel						WIND	L02					SNOW	Comp Time -			518 T	TRUCK-MOVING/E	BOX/BOARD UF	
	9/6/24							MOLD MOLD		L03					RAIN	Hold (explain why in descript			523 T	TRUCK, 3/4 TON P	PICKUP
CREW SHEET# 80 E WackerPl							EART	L04					WINDY	HOIC	(explain willy	Ti description)	527 T	TRUCK, 1 TON 4X4	4 W/LIFTGATE		
LAST 3 LETTERS OF JOB NAME-6 DIGIT DATE-LAST 3 #'S OF VERIFIERS JDE Chicago IL									L05						Othe	ſ		453 T	TRUCK, EXTRACTIO	ON	
TE	1 - 90	0624 - 994	SAFETY TOPIC			TOOL BOX TRA				L06						Contact			N/A 1	NO VEHICLE	
			PPE			COMPLETED?										Lockbo	x / Other Code	:	FOR RENTA	AL CARS: HICLE CODE AND	CHECK BOX
OFFICE		PERSONNE	PERSONNEL NAME		24 HOUR	24 HOUR CLOC	24 HOUR	TOTAL HOURS	Z		HOURS	ς			SEE GUI	DE SHEET SEE TABLE		=	PERSO	NNEL NAME	
	ID#	CLEARLY PRINT YOUR NAME HELPS ENSU PAID FOR HOURS WORKED. AN ILLEGIBLE		RATE CLASS	START TIME	START TIME STOP TIME		CONFIRM HOURS BY PERSON BY OTHER	LOCATION CODE	PHASE CODE	BY	TOOLS	r test	- HARNESS DIEM	NAME	0	_ viiitii			NTS THE APPROVAL D. A LACK OF SIGNAT	
		NO PA										 	P - FIT	P - HA			H CODE			MELY OR NO PAY	
1		PRINT FIRST <u>THEN</u> LAST NAME			11141					WED		SMA	PRP	PFP PER		-	., 527	SI	GNATUR	E- END OF SH	IIFT VERIFIE
1011	1910994	Gustavo	Galvez		700	1200	1400	6.50	L00	WTR	6.50	N N	N	NN	NA	NA	N SZT RENTA	_			GG
2			т 1		700	1200	1 400	6.50	L00	WTR	6.50				N.T.A	NIA	520				VERIFIE
1011	1632176	Jordan H	lankey		700	1230	1400					N N	I N	N N	NA	NA	RENTA				GG
3	707	Wilson Ro	Arianez		700	1200	1400	6.50	L00	WTR	6.50	N N	ı N	N N	NΔ	NA	N/A				VERIFIE
1011	707 WISOII IXC		Junguez		700	1230	1400						\perp	+			RENTA	-	GG VERIFIE		
4												N	ı N	N N			N RENTA				VERIFIE
5													+	+			L_IRENTA	-			VERIFIE
												N	I N	N N			N RENTA	ı l			
6												N N	ı N	N N			N				VERIFIE
												1					RENTA				
7												N N	ı N	N N			N -	-			VERIFIE
8								-				_	+	-			RENTA	-			VERIFIE
												N	I N	N N			N RENTA	_			
9																					VERIFIE
												N N	I N	N N			N RENTA	_ L			
10												NN	ı N	N N			N				VERIFIE
11																	RENTA	-			VERIFIE
11												N	I N	N N			N RENTA				VERIFIE
12												_	+	+			LRENTA	-			VERIFIE
												N N	I N	N N			N RENTA				
13												NI N	ı Nı	N N			N				VERIFIE
												1					RENTA				
14												N N	ı N	N N			N -	-			VERIFIE
RESPONSIB	LITY OF APPROVER:	PLEASE COMPLETE ALL REQUESTS BELOW						VERIFY TOTAL HRS	<u> </u>		↑ VERIFY TOTA	I HRS			VERIFICAT	ION OF PTS DA	TA RENTA		VER SIGNATURE	TO VERIFY FORM IS COI	 DMPLETED
	STEP 1-PRINT APPROV		STEP 3-TOTAL HRS	O TOTALS	TALS STEP 4-PHASE HRS			STEP 5 - DOES THE PTS					STEP 6-APP	ROVER SIGNATURE							
Jordan Hankey IF "N", YOU MUST VERIFY & COMPLETE ALL OUTSTANDING ISSUES INCLUDING TOP SECTION OF FORM								19.5 ≤ should M		MATCH	1 401			WHO		VHERE □WHEN WHERE □WHY □HOW		(Danda	n Hanke	,,
WORK DE		INCLODING		ESCRIBE W	HAT WORK TI	HE CREW PERF	ORMED	1010					WUK	K DESC:	WHAI	WHEKE	Twu Thou	6	Je aca	" Transa	7
I called for the emergency upon arriving to the warehouse. We are loaded the emergency truck with the necessary tools that were needed for the job. Once arriving at the job site we met with the maintenance Cisco. He showed us the units that were affected after showing us the units. We went back to the truck and unloaded the necessary tools that we needed to start the job first we																					
1	•	the water on the on t																•		•	
		n to unit 1230 and w												_					•		
	_	9 through 20% set up light to check those u					_														•
_	_	ight to check those to the hallway there w		_		-	-														_
		idn't leave DQ today	11 0							ou unu	. Рошин	5 m		oo mir	p procii	ою пп	.anviuy III (I		voi in al	m wot wo	on oura
		•				•				05.54	CE			# 05 5	۸۵۶ ۲	\neg			Г		
FURM V	KIFIEK-PLEASE	CHECK BOX AND ENTER QU	JANTITY FOR A E& PA	AGEST CL	UUŁD WITH	THIS SHEET	L	NONE	L	OF PA	GE	l	Ш	# UF P	AGE 5	_	RECIEP	T TRACKING	FORMS _		

PAGE 1 SIMPSON 052317