Evaluation Warning: The document was created with Spire.PDF for Python.

Evaluation Warning: The document was created with Spire.PDF for Python.

PERSONNEL TRACKING

PERSONNEL TRACKING

SEDVICE TYPE (DESTORATION)



							SERVICE	TYPE (KES	TUKAT	ION)										PROP	entvallion	ATION
S DOC # CTRONIC	FORM VERIFIER L	INE# 1 INITIALS Bn	JOB NUMBER-COMPLETE	1011	00460			LOSS CAUSE FIRE		CODE	Site				WEATHER		JOB STATUS				EHICLE NAME (TABLE)
	START DATE	START DAY		10110	08469					L00					HUMID	N	ew		RETURN	529 PI	CKUP, SUV OR CAI	R
	9/4/24	Wednesday					WATER/FLOOD		L01				TEMP 7	5 Ongo	ing	Date -		530 VA	AN, PASSENGER/C	ARGO		
	STOP DATE	_ = 3.9.13.1 3 , 113.1.3.						WIND		L02			· [SNOW	Coi	тр [Time -		518 TR	RUCK-MOVING/BO)X/BOARD UP	
	9/4/24	Wednesday	JOB ADDRESS			MOLD MOLD		L03					RAIN		Hold (explain why in do			523 TP	RUCK, 3/4 TON PIC	CKUP		
CREW SHEET# 1105 McCall Ct								EARTHQUAKE		L04				_ [WINDY	H	old [_	(explain why in	description)	527 TP	RUCK, 1 TON 4X4 V	W/LIFTGATE
LAST 3 LETTERS OF JOB NAME-6 DIGIT DATE-LAST 3 #'S OF VERIFIERS JDE RochellelL							L05						Oth	her			453 TF	RUCK, EXTRACTION	N			
NIE - 90424 - 109 SAFETY TOPIC					TOOL BOX TRAINING				L06				- <u>-</u>		Conta	act:			N/A NO	O VEHICLE		
NIC - 90424 -		U 1 2 1 - 109	Steel toe			COMPLETED?										Lock	Lockbox / Other Code:			FOR RENTAL CARS: FILL IN VEHICLE CODE AND CHECK BOX		
		PERSONNE	L NAME			24 HOUR CLOC		TOTAL HOURS	z		HOURS	(0	Т		SEE	GUIDE SHEET	Σ	SEE TABLE			INEL NAME	ILECK BOX
OFFICE	ID#	CLEARLY PRINT YOUR NAME HELPS ENSURE THE CORRECT PERSON IS BEING PAID FOR HOURS WORKED. AN ILLEGIBLE NAME MAY RESULT IN UNTIMELY C		RATE	24 HOUR	START TIME	24 HOUR	CONFIRM HOURS	LOCA	PHASE CODE DMO	PHASE 3	_00F	N PPE N PRP - FIT TEST	RNESS	≥ HOT		- 1 4	VEHILLE	YOUR SIGNAT		ITS THE APPROVAL TO . A LACK OF SIGNATUR	
			NO PAY		START TIME		STOP TIME	BY PERSON BY OTHER				IALL T		- HAR	H COD		HARE W	CODE			ELY OR NO PAY	NE WINT NESSET
1		PRINT FIRST <u>THEN</u> LAST NAME		\square	IIIVIL	STOP TIME	111111					SMAL		PFP	# COD	- "	S	507	SIC	SNATURE	-END OF SHIF	F T VERIFIER
1011	1793109	Brian Nork			700	1200	1700	9.50				N		N	N N	a Na	$a \mid N$	527 RENTAL				Bn
2						1200		9.25	L00	DMO	9.25		+	\vdash				N/A				VERIFIER
1011	707	Esp eranza osorio			700	1230	1645	7.23	200	Divio	7.20	N I	N N	N	N N	a Na	1 N	RENTAL				Bn
3	707	Androgon	istiza bal		700	1200	1645	9.25	L00	DMO	9.25	N N	N N	N	N Na	Nic		N/A				VERIFIER
1011 707		Andres aristizabal			700	1230	1043					IN		14	" IN	a Na	1 "	RENTAL				Bn
1011	707	Leonard	lo diaz		700	1200	1645	9.25	L00	DMO	9.25	N I	N N	N	N Na	a Na	a N	N/A				verifier Bn
1 011	707	Leonare		700	1230	1013	-				+	+	Н	7.40	1 110	+	RENTAL				VERIFIER	
												N I	N N	N	N		N	RENTAL				
6																	١.					VERIFIER
												N I	N	N	N		N	RENTAL				
7												N I	J N	N	N							VERIFIER
													<u> </u>	ļ.,			ļ.	RENTAL				VEDIEIE
8												N I	N N	N	N		N					VERIFIER
9												+	+	\vdash	_		+	RENTAL				VERIFIER
												N I	N N	N	N		N	RENTAL				
10												, ,		N.	N.							VERIFIER
												IN I	111	N	IN			RENTAL				
11												N I	N N	N	N		N	ı <u> </u>				VERIFIER
12												+	+	Н			+	RENTAL				VERIFIER
12											\vdash	N	N N	N	N		N	RENTAL				VERMILE
13												+	+	\vdash			+					VERIFIER
												1 N	N N	N	N		N	RENTAL				
14												N I	J	N	N			,				VERIFIER
								VERIFY TOTAL HR					`	''				RENTAL				
RESPONSIBILITY OF APPROVER: PLEASE COMPLETE ALL REQUESTS BELOW STEP 1-PRINT APPROVER NAME STEP 2-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION?									THESE TW	VERIFY TOTAL HRS O TOTALS STEP 4-PHASE HRS					VERIFICATION OF PTS DATA STEP 5 - DOES THE PTS COVER:				APPROVER SIGNATURE TO VERIFY FORM IS COMPLETED STEP 6-APPROVER SIGNATURE			
Jordan Hankey Jordan Hankey							_	SHOULD				5	\top	□w		WHERE		WHEN		Onda	· dayla	
		INCLUDING - ON LOCATION(S) WORKED AN	TOP SECTION OF FORM	ECCDIDE VA	ILAT MODE T	HE CDEW DEDE	OPMED	37.25		\rightarrow	31.2	.5	wo	RK DESC	: WHAT	WHERE		why _ How		Joraa	n Hankey	<u></u>
Got 1	to the sh	op loaded up	truck with equ	uipmo	ent an	d ma te	rials I	need it	t for to	oda y.	. We o	dro	ve	to	Rocl	ne lle	hc	ouse or	ı McCa	ıll Ct.	upon	
arriva	al we en	tered the home	e we remove	d the	2 doc	or iams	and d	loors in	nant	rv. W	le the	n 1	e n	10 1	ed k	itche	n f	loor all	the wa	av to	sub flo	or.
		all inside wind				U			1	•										•		
											uone	, J	. 110	711 V	WC 1C	IIIO V	Cu	all Ual	11100111	пупп	ng non	1 a 11
bath	rooms. T	Then we starte	d to remove	stapl	es troi	n launc	ary an	d kitche	en flo	ors.												
FORM VE	RIFIFR-PI FASF	CHECK BOX AND ENTER QU	IANTITY FΩR Δ F& DΔ	GESI (1	UDFD W/ITH	H THIS SHEFT	Γ	NONE		OF PAG	GF		Г]# OF	PAGE 5	\neg		RECIEPT	TDACKING	FORMS	$\overline{}$	
. J. M.F. V.L		J. LONDON MID LITTLIN QU			.JULU VVIII		L		ш	J. 1710		I		7 Č,				L KECIEPI	INACKING	I OVIND		

SIMPSON 052317 PAGE 1