Evaluation Warning: The document was created with Spire.PDF for Python.

Evaluation Warning: The document was created with Spire.PDF for Python.

PERSONNEL TRACKING

PERSONNEL TRACKING



SERVICE TYPE (RESTORATION)													Tion									
<u></u>	FORM VERIFIER L	M VERIFIER LINE # 1 INITIALS GG JOB NUMBER-COMPLETE						LOSS CAUSE		CODE	LOCATION				WEATHE			JOB STATUS		CODE VEHICLE NAME (TA	ABLE)	
PTS DOC# ELECTRONIC	START DATE	START DAY 101108486						☐ FIRE ☐ WATER/FLOOD		L00					HUMIC		New		RETURN	529 PICKUP, SUV OR CAR		
DOC	9/3/24	Tue sd a y								L01				_ [	TEMP	78 Ong	oing	Date -		530 VAN, PASSENGER/CAR	RGO	
PTS ELEC	STOP DATE	4700 5 500 0 1						WINE	)	L02					SNOW		omp	Time -		518 TRUCK-MOVING/BOX/	/BOARD UP	
" "	9/3/24	Tuesday	JOB ADDRESS					<b>П</b> моц	D	L03				- =	RAIN			<del></del> -		523 TRUCK, 3/4 TON PICKL	UP	
CREW SHEET# 1700 E 56th St									HQUAKE	L04					WINDY		Hold (explain why in descr			527 TRUCK, 1 TON 4X4 W/		
LAST 3 LETTERS OF JOB NAME-6 DIGIT DATE-LAST 3 #'S OF VERIFIERS JDE Chicago IL							Ħ		L05				- 7	7		ther			453 TRUCK, EXTRACTION			
NIDO 00224 OO4 SAFETY TOPIC				TOOL BOX TRAINING		<u> </u>		L06					┪	Cor	Contact:			N/A NO VEHICLE				
NDO - 90324 - 994   SAFETY TOPIC   PPE							COMPLETED?		ш								Ŀ	Other Code	. —	FOR RENTAL CARS:		
		PERSONNEI				24 HOUR CLOCK		TOTAL HOURS Z					$\top$		SE	CHIDE CHE	UDE CUEET			FILL IN VEHICLE CODE AND CHE PERSONNEL NAME	ECK BOX	
OFFICE	ID#	CLEARLY PRINT YOUR NAME HELPS ENSURE THE CORRECT PERSON IS BEING		RATE	24 HOUR	LUNCH	24 HOUR	CONFIRM HOURS	. 0	PHASE	HOURS	OOLS	TEST	ESS	НО	TEL HO	TEL S	Ş VELUCI E	YOUR SIGNAT	YOUR SIGNATURE REPRESENTS THE APPROVAL TO PAY YOUR		
		PAID FOR HOURS WORKED. AN ILLEGIBLE NO PA		CLASS	START	START TIME	3101	BY PERSON	CAT	CODE	BY	LL TC	=	- HARN	NA DE MA		OM		DOCUMENTED HO	OURS WORKED. A LACK OF SIGNATURE I IN UNTIMELY OR NO PAY	MAY RESULT	
		PRINT FIRST <u>THE</u>	ST <u>THEN</u> LAST NAME		TIME	STOP TIME	TIME	BY OTHER	2		PHASE	SMAI	PRP	PFP.	PER CO	DE #	ŧ   3	TS CODE	SI	GNATURE-END OF SHIFT		
1	1910994	Guetava	Calvar		700	1200	1 / 1 / 5	6.75	L00	WTR	6.75	N N	ı N	N	N NI	AN	$\overline{\mathbf{A}}$	530			VERIFIER	
1011	1910994	Gustavo Galvez			700	1230	1415								" 11	AIN	A '	L INCINIAL			GG	
1011	707	Wilson rodriguez			700	1200	1415	6.75	L00	WTR	6.75	N	I N	N	N	A   N	$A ^{\mathfrak{l}}$	N/A RENTAL			verifier GG	
3	707	Eraddy	70 10 to		700	1200	1415	6.75	L00	WTR	6.75	N N	I N	N	N NI	AN	A	N/A			VERIFIER	
1011	707 Freddy za		za pa ta		/00	1230	1413					10 10		"	" 11	AIN	A '	RENTAL			GG	
4											$\vdash$	N N	I N	N	N		1	N RENTAL			VERIFIER	
5												N N	ı N	N	N			<u> </u>			VERIFIER	
												IN I	1	IN	IN			RENTAL				
6											$\vdash$	N N	ı N	N	N		ı	N			VERIFIER	
7													+	$\vdash$			+	RENTAL			VERIFIER	
												N	I N	N	N			N RENTAL				
8												N N	ı N	N	N		1	,			VERIFIER	
٥												_	+	$\vdash$		_	_	RENTAL			VERIFIER	
9											-	N	I N	N	N		1	N RENTAL	-		VENIFIER	
10													+	$\vdash$				KENTAL			VERIFIER	
												N	I N	N	N			RENTAL				
11												NN	ı N	N	N			N .			VERIFIER	
12													<u> </u>	L'`			<u> </u>	RENTAL			VERIFIER	
12											$\vdash$	N	I N	N	N		ı	N RENTAL	-		VERIFIER	
13												N N	ı N	N	N			<u> </u>			VERIFIER	
14														+"	.,	_		RENTAL			VERIFIER	
											$\vdash$	N	I N	N	N		ľ	N RENTAL			VEINITEIN	
RESPONSIBILITY OF APPROVER: PLEASE COMPLETE ALL REQUESTS BELOW								VERIFY TOTAL HR	S		↑ VERIFY TOTAL HRS				VERIFICATION OF PTS DATA					ER SIGNATURE TO VERIFY FORM IS COMPLET	TED	
STEP 1-PRINT APPROVER NAME STEP 2-DID THE FORM VERIFIER REVIEW THIS FORM FOR COMPLETION IF "N", YOU MUST VERIFY & COMPLETE ALL OUTSTANDING ISSUES						ION?	DN?		STEP 3-TOTAL HRS THESE TWO SHOULD I		STEP 4-PHASE HRS				STEP 5 - DOES THE PTS COVER:					STEP 6-APPROVER SIGNATURE		
Jordan Hankey  INCLUDING TOP SECTION OF FORM  WORK DESCRIPTION: BASED ON LOCATION(S) WORKED AND PHASE CODE(S), PLEASE DESCRIBE WHAT WORK THE									20.25					WHO WHERE WHEN DESC: WHAT WHERE WHY HOW				(	Jordan Hankey			
		. ,																		<i>U</i>		
Arriv	red at the	e warehouse, l	oaded the va	n wit	th the 1	ne ce ss	a ry to	ols onc	e arr	iving	to job	) si	te	we	me	up	witl	n Alliso	n so sh	re could get r	18	
		We did moistur					•			_	•					-						
			<del>-</del>					_							_				ary contra	, , o i wii w	.•	
302	aic Silli '	wet and we har	ve to wait off	uic l	CHallt	on ull	ιυυ∠ S	o we c	oulu	uu II.	io ist u.	ו כו	UC	ıul	ngs l	11 116	ı U	1111				
FORM VI	RIFIER-PI FASF	CHECK BOX AND ENTER QU	IANTITY FOR A F& PA	GES I CI	UDFD WITH	I THIS SHEET	. Г	NONE		OF PAG	GE		Т	# O	F PAGE 5			DECIED	T TRACKING	EOPMS		
. JANTI VI		J. ILON DOM MIND LIVILIN QU		.J.J. CL	.JJLU VVIIII	JIILLI	L	<b>_</b>		J. IA	~ <b>-</b>		<b>L</b>	J., Č				L KECIEP	IKACKING	LOVINI2		

PAGE 1