EX.NO.1.1-DESIGN AND DRAFT THE GIVEN 2D SKETCHES IN MODELLING SOFTWARE.

AIM

To sketch the given drawing with dimensions using a fusion 360 tool.

REQUIREMENTS

- *Computer or laptop*
- *Autodesk fusion*
- *Mouse and keyboard*
- *Windows 10*

PROCEDURE

★ *Open Autodesk Fusion and select Create sketch.*

★ *Draw a circle at the center with Ø40mm.*

★ *Draw the inner shape using circles and arcs with Ø12mm.*

★ *Draw the outer circle with Ø20mm and inner circles with Ø14mm*

★ *Draw top circles with Ø32mm and inner circle with Ø20mm.*


★ *Draw a circle outside with Ø128mm and Ø66mm.*

★ *Set the vertical dimensions to 69mm,25mm, and 24mm.*

★ *Set horizontal distance to 47mm.*

★ *Use a mirror option to copy the sketch to the opposite side of the center line.*


★ *Use a trim tool to remove unwanted lines.*




★ *Check all dimensions and close the sketch which is in the top right corner.*

★ *Save the design.*

★ *Select an extrude option which is on top left. Then select an object to extrude and give the extrude distance –15mm.*




★ *Then select the design option and click on the drawing mode (from the design).*




★ *And finally save it.*

SKETCHES



OUTPUT



RESULT

Thus, the given sketch is drawn and drafted using a fusion 360 tool.