EX.NO.1.2-DESIGN AND DRAFT THE GIVEN 2D SKETCHES IN MODELLING SOFTWARE.

AIM

To sketch the given drawing with dimensions using a fusion 360 tool.


REQUIREMENTS

- *Autodesk fusion 360*
- *Windows 10*
- *Mouse and Keyboard*
- *Computer and Laptop*

PROCEDURE


- *Open Autodesk fusion and select the sketch option.*
- *Select the front plane and draw a circle at the origin using the Circle command.*

- *Give the required diameter expression using the dimension command.*
- *Draw the inner circles and other required circles with the given dimension.*
- *Draw the outer profile using the Line and Arc commands.*
- *Select the required geometry and use the Mirror command to create the same geometry on the opposite side by selecting the x-axis center line.*
- *Repeat it until you get a complete design.*
- *Use the trim tool to remove unwanted lines.*




- *Check all dimensions and close the sketch which is in the top right corner.*
- *Save the design.*

- *Select an extrude option which is on top left. Then select an object to extrude and give the extrude distance –20mm.*




- *Then select the design option and click on the drawing mode (from the design)*




- *And finally save it.*

SKETCHES


Exercise1.2* (pradeep) - Autodesk Fusion (Education License)
Exercise1.2*
SOLID
SURFACE
MESH
SHEET METAL
PLASTIC
MANAGE
UTILITIES
SKETCH
DESIGN
CREATE
MODIFY
CONSTRAINTS
CONFIGURE
INSPECT
INSERT
ASSEMBLE
SELECT
FINISH SKETCH
BROWSER
Exercise1.2
Document Settings
Named Views
Origin
Sketches
Ø64.00
Ø80.00
Ø32.00
Ø40.00
Ø30.00
Ø42.00
Ø40.00
Ø30.00
Ø42.00
FRONT
SKETCH PALETTE
Options
Linetype
Look At
Sketch Grid
Snap
Slice
Profile
Points
Dimensions
Constraints
Projected Geometries
Construction Geometries
3D Sketch
Finish Sketch
COMMENTS
29°C
Light rain
Search
ENG
IN
59%
16:46
15-10-2026

OUTPUT



RESULT

Thus, the given sketch is drawn and drafted using a fusion 360 tool.