Ardustat V8 board description. Since the Digital I/O pins have been reversed the switch has been made in firmware 8. Pin 0 needs to be cut and shorted to Pin 3.