

**AMENDMENT NO. 1 JUNE 2011
TO
IS 15785 : 2007 INSTALLATION AND MAINTENANCE
OF LIFT WITHOUT CONVENTIONAL MACHINE
ROOMS — CODE OF PRACTICE**

(Page 2, clause 4.4.5, Title) — Substitute ‘*Suspension Media*’ for the existing.

(Page 2, clause 4.4.5, para 4) — Substitute the following for the existing:

‘Coated Steel Belts (CSB) used shall comply with Annex B. Ratio of sheave diameter to steel cord shall remain 40 : 1 and minimum factor of safety on CSB breaking strength shall be 12. Minimum 2 CSB's shall be used. Each Lift shall be provided with detection device or mechanism which will bring elevator to stop in case of elongation of belt or breakage of one belt. The device shall not be of automatic reset type and shall require intervention of competent person to reset the same.’

(Page 9, Annex B, clause B-7.2.2.7) — Add the following new clause:

‘B-7.3 Visual Check and Replacement Criteria

CSB's shall be inspected visually. If any of the following defects are observed in visual inspection, all the CSB's shall be replaced:

- Visual damage such as a kink in CSB, exposed cords, excessive elastomeric coating wear, etc
- Steel cords, strands or wires breaking through its elastomeric coating
- Piercing of CSB by foreign object
- Damaged CSB edge where outermost cord is visible.’