

AMENDMENT NO. 1 JULY 2017
TO
IS 4839 (PART 2) : 1992 MAINTENANCE OF CANALS —
CODE OF PRACTICE

PART 2 LINED CANALS

(Second Revision)

(Page 1, clause 2) — Insert the following new entry at an appropriate place:

<i>IS No.</i>	<i>Title</i>
4701 : 1982	Code of practice for earthwork on canals

(Page 2, clause 3.4.1, sentence 1) — *Substitute* 'Any cavities or pockets detected behind the lining should be carefully packed with sand or other suitable material' *for* 'Any activities or pockets detected behind the lining should be carefully packed with sand or other suitable material'.

(Page 2, clause 3.4.8) — Insert the following new clause after **3.4.8**:

'3.4.9 In case any settlement takes place in the embankment (*see* IS 4701)'.