


AMENDMENT NO. 1 JANUARY 1990
TO
IS : 2223 - 1983 DIMENSIONS OF FLANGE
MOUNTED AC INDUCTION MOTORS

(Second Revision)

(Explanatory Note — The symbol of eccentricity 'e' has been deleted as the same is already incorporated through the graphical engineering drawing symbols).

(Page 8, Fig. 1) — Substitute the following for the existing figure:




NOTE 1 — Symbols are standardized to facilitate reference when ordering motors to this standard. The ringed symbols refer to dimensions which are specified in this standard.

NOTE 2 — The shoulder of the shaft should be in the same plane as the face of the flange, that is, dimension R would be zero with normal tolerances.

FIG. 1 MOTORS WITH B-TYPE FLANGE

(Page 8, Fig. 2) — Substitute the following for the existing figure:




NOTE 1 — Symbols are standardized to facilitate reference when ordering motors to this standard. The ringed symbols refer to the dimensions which are specified in this standard.

NOTE 2 — The shoulder of the shaft should be in the same plane as the face of the flange, that is, dimension R would be zero with normal tolerances.

FIG. 2 MOTORS WITH C-TYPE FLANGE

(Page 9, Fig. 3) — Substitute the following for the existing figure:



NOTE — Symbols are standardized to facilitate reference when ordering motors to this standard. The ringed symbols refer to dimensions which are specified in this standard.

FIG. 3 MOTORS WITH D-TYPE FLANGE


(ETDC 15)

AMENDMENT NO. 1 JANUARY 1990
TO
IS : 2223 - 1983 DIMENSIONS OF FLANGE
MOUNTED AC INDUCTION MOTORS

(Second Revision)

(Explanatory Note — The symbol of eccentricity 'e' has been deleted as the same is already incorporated through the graphical engineering drawing symbols).

(Page 8, Fig. 1) — Substitute the following for the existing figure:



NOTE 1 — Symbols are standardized to facilitate reference when ordering motors to this standard. The ringed symbols refer to dimensions which are specified in this standard.

NOTE 2 — The shoulder of the shaft should be in the same plane as the face of the flange, that is, dimension R would be zero with normal tolerances.

FIG. 1 MOTORS WITH B-TYPE FLANGE