

**AMENDMENT NO. 2 APRIL 2002
TO
IS 13827 :1993 IMPROVING EARTHQUAKE
RESISTANCE OF EARTHEN BUILDINGS — GUIDELINES**

(*Page 1, clause 3.5*) — Substitute the following for the existing:

‘3.5 Seismic Zone and Seismic Coefficient

The seismic zones II to V as classified and the corresponding zone factors as specified in 6.4.2 (Table 2) of IS 1893 (Part 1)‘.

(*Page 1, clause 3.6*) — Substitute the following for the existing:

‘3.6 Zone Factor (Z)

It is a factor to obtain the design spectrum depending on the perceived maximum seismic risk characterized by maximum considered earthquake (MCE) in the zone in which the structure is located.’

[*Page 4, clause 10.1.7 (see also Amendment No. 1)*] — Substitute ‘Zone II’ for ‘zones I and II’.

[*Page 6, clause 11.1 (see also Amendment No. 1)*] — Substitute ‘Zone II’ for ‘zones I and II’ .

(CED 39)