

**AMENDMENT NO. 2 APRIL 2002
TO
IS 13828 : 1993 IMPROVING EARTHQUAKE
RESISTANCE OF LOW STRENGTH MASONRY
BUILDINGS — GUIDELINES**

{ *Page 1, clause 1.1.1 (see also Amendment No. 1)* } — Substitute 'zone II' for 'zones I and II'

(*Page 1, clause 3.6*) — Substitute the following for the existing:

3.6 Seismic Zone and Seismic Coefficient

'The seismic zones II to V as classified and the corresponding zone factors as specified in 6.4.2 (Table 2) of IS 1893 (Part 1).'

(*Page 1, clause 3.7*) — Substitute the following for the existing:

3.7 Zone Factor (Z)

It is a factor to obtain the design spectrum depending on the perceived maximum seismic risk characterized by maximum considered earthquake (MCE) in the zone in which the structure is located.'

(CED 39)