

AMENDMENT NO. 2 JUNE 2013
TO
IS 1727 : 1967 METHODS OF TEST FOR
POZZOLANIC MATERIALS

(First Revision)

(Page 7, clause 5.2, sentence 1) — Insert the following after sentence 1:

‘Keep about 10 g sample in a large glass Petri dish and spread it evenly into a thin layer. Put it in the oven maintained at $105\text{ }^{\circ}\text{C} \pm 5\text{ }^{\circ}\text{C}$ for 1h to remove any superficially adsorbed moisture. Take it out and keep in a desiccator and cool it to room temperature for chemical analysis.’

(Page 8, clause 5.3) — Substitute the following for the existing clause:

‘5.3 Loss on Ignition

Heat about 1g of oven dried sample, m_1 (accurately weighed up to four decimal place) for 15 min in a weighed and covered platinum crucible (a porcelain crucible may also be used) of 20 to 25 ml capacity by placing it in a muffle furnace at a temperature between $900\text{ }^{\circ}\text{C}$ and $1\ 000\text{ }^{\circ}\text{C}$; cool and weigh. Check the loss in mass by a second heating for 5 min and reweigh (m_2). Calculate the loss on ignition as follows:

$$\text{Percent loss on ignition} = \left(\frac{m_1 - m_2}{m_1} \right) \times 100$$

Round off the calculated value and report up to 1 decimal place.

NOTE — The significance of the determination of loss on ignition shall vary according to the nature of the sample. The figure obtained may include loss due to the oxidation of any carbonaceous matter and gain due to the oxidation of any ferrous iron present.’

(Page 8, clause 5.4.1, line 1) — Substitute ‘Fuse about 1g of the oven dried (accurately weighed up to four decimal places)’ for ‘Fuse one gram of the air dried’.

(CED 2)