

AMENDMENT NO. 1 JULY 1990
TO
IS : 1255 - 1983 CODE OF PRACTICE FOR
INSTALLATION AND MAINTENANCE OF POWER
CABLES UP TO AND INCLUDING 33 kV RATING

(Second Revision)

(Page 7, clause 4.2.1.2) — Insert the following after 4.2.1.2:

'4.2.1.3 Route indicators — Power cable route indicators should be provided at an interval not exceeding 200 M and also at turning points of the power cable route wherever practicable.'

(Page 17, clause 6.3.3) — Insert the following after 6.3.3:

"6.3.3.1 The power cable should not be laid above the telecommunication cable, to avoid danger to life of the person, digging to attend to the fault in the telecommunication cable.

6.3.3.2 For identification of power cables, the cable protective cover, such as bricks or RCC slabs may be suitably marked by words 'power cable' or 'by the owner'.

6.3.3.3 While laying power cables, the likely interference to existing telecommunication cables should be avoided by referring to and coordinating with the appropriate telecommunication authorities."

(Page 60, Table 6, col 4) — Substitute '15' for '5'.

(ETD 9)