

AMENDMENT NO. 1 FEBRUARY 1990
TO
IS : 12100 - 1987 SPECIFICATION FOR HIGH
DENSITY POLYETHYLENE (HDPE) WOVEN
SACKS FOR PACKING FLOUR

(Page 7, clause 5) — Substitute the following for the existing clause:

'5. SAMPLING AND CRITERIA FOR CONFORMITY

5.1 In any consignment all the sacks of the same construction shall be grouped together to constitute a lot.

5.2 The conformity of the lot to the requirements of the standard shall be determined on the basis of the test carried out on the samples selected from it.

5.3 Unless otherwise agreed to between the buyer and the seller the number of bales to be selected depends on the size of the lot and shall be in accordance with col 1 and 2 of Table 2. Also the number of sacks to be selected from the bale samples shall be in accordance with col 4 of Table 2 for visual dimensional and mass requirements and shall be in accordance with the col 1 of Table 2 for breaking load requirements.

5.4 Number of Tests and Criteria for Conformity

5.4.1 *Visual, Dimensional and Mass Requirement* — Test for the visual, dimensional and mass requirements (**2.1** to **2.5** and **3.2** and **3.3**) for ascertaining the conformity of the lot shall be made on the sample sacks selected in one or two stages as the case may be (*see* Table 2).

5.4.1.1 The sample sacks selected in the first stage shall be examined for various requirements specified. Any sack failing to satisfy one or more requirements shall be termed as defective. If the number of defective in the first stage is less than or equal to the acceptance number (A) given in col 6 of Table 2 the lot shall be accepted. If the number of defectives is equal to or greater than the rejection number (r) given in col 7 of Table 2 the lot shall be rejected. If it lies between (A) and (r) for the first stage, a second sample of size given in col 3 of Table 2 shall be added if this cumulative number is less than or equal to the acceptance number for the second stage, the lot shall be accepted. If the cumulative number of defective is equal to or greater than the corresponding rejection number, the lot shall be rejected without further testing.

5.4.2 *Breaking Load Requirements* — Test for the breaking load requirement (**3.1**) for ascertaining the conformity of the lot shall be made on the sample sacks selected in one or two stages as the case may be (*see* Table 2).

5.4.2.1 The samples sacks selected and tested shall be as per the procedure followed in **5.4.1.1**. However, the acceptance number (*A*) shall be as given in col 10 of Table 2 and the rejection number (*r*) shall be as given in col 11 of Table 2.'

(Page 7, Table 2) — Substitute the following for the existing table:

TABLE 2 SAMPLE SIZE AND CRITERIA FOR CONFORMITY

(Clauses 5.3 and 5.4)

No. OF BALES IN THE LOT	No. OF BALES TO BE SAMPLFD		VISUAL, DIMENSIONAL AND MASS REQUIREMENTS				STRENGTH REQUIREMENTS			
	(2)	(3)	Sample Size (sacks)	Cumulative Sample Size (sacks)	<i>A</i>	<i>r</i>	Sample Size (sacks)	Cumulative Sample Size (sacks)	<i>A</i>	<i>r</i>
(1)			(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
Up to 25	3	I stage	13	13	0	3	8	8	0	1
		II stage	13	26	3	4	—	—	—	—
26 to 50	5	I stage	20	20		4	8	8	0	1
		II stage	20	40	1	5		—	—	—
51 to 100	8	I stage	32	32	4	5	11	13	0	2
		II stage	32	64	6	7	13	26	1	2
101 and above	12	I stage	50	50	3	7	20	20	0	3
		II stage	50	100	8	9	20	40	3	4

(TXD 23)