

**AMENDMENT NO. 1 OCTOBER 2009
TO
IS 819 : 1957 CODE OF PRACTICE FOR
RESISTANCE SPOT WELDING FOR LIGHT
ASSEMBLIES IN MILD STEEL**

(Page 6, clause 4) — Substitute ‘EQUIPMENT’ for ‘PLANT’.

(Page 6, clause 4.1.1, second sentence) — Delete.

(Page 7, clause 6.1.1, line 2) — Substitute ‘reasonable’ for ‘practicable’.

(Page 7, Table 1, col 2) — Insert ‘*’ after the word ‘Current’.

(Page 7, Table 1) — Insert the following footnote at the end:

‘*Fine tuning of current control may require the use of phase shift control.’

[Page 7, Table 1, Sl No. (iii)] — Substitute ‘Squeeze’ for ‘Pressure’.

(Page 7, clause 6.2.1, last line) — Delete ‘and in foot-pound units in Table IIA’.

[Pages 7 and 8, clauses 6.2.1.1 and 6.2.1.2] — Delete ‘(or 10 000 lb/in²), (or 15 000 lb/in²), (or $\frac{5}{16}$ in) and

(or $\frac{11}{32}$ in) wherever appears.

(Page 10, Table II, col heading 4) — Substitute ‘Hz’ for ‘c/s’.

(Page 11, Table IIA) — Delete.

(Page 12, Annex A, clause A-2.1) — Add the following new line at the end:

‘e) Whenever an operator is changed.’

(Page 14, Annex A, clause A-3.1, line 1) — Substitute ‘peeled’ for ‘prized’.

(Pages 16 and 17, Annex B, clauses B.1.1(a), (b), (c), and (f); B.2.1(a), (c), and (f); and B-2.2) — Substitute ‘squeeze’ for ‘welding pressure’ wherever appears.

Amend No. 1 to IS 819 : 1957

(Page 19, Annex C, clause C-3.4, lines 1 and 2):

a) Add the word ‘be’ in between the words ‘to’ and ‘increase’.

b) Substitute the word ‘increased’ for ‘increase’.

(Page 19, Annex C, clause C-3.5, line 1) — Substitute ‘frequently depending on production’ *for* ‘time to time’.

(Page 19, Annex C, clause C-4.1, lines 3 and 4) — Delete ‘(or $\frac{5}{16}$ in)’.

(Page 19, Annex C, clause C-5.1, lines 5 and 7) — Delete ‘(or 0.50 in)’.

(MTD 12)

Reprography Unit, BIS, New Delhi, India