

**AMENDMENT NO. 1 OCTOBER 2009
TO
IS 8987 : 1978 RECOMMENDED PRACTICES FOR
AIR CARBON ARC GOUGING AND CUTTING**

(Page 3, clause 0.2, line 3) — Substitute ‘cut’ for ‘out’.

(Page 13, clause 12.1, last para under column Technique) — Substitute the following for the existing:

‘These metals are suitable for air carbon-arc cutting process’.

[Page 15, clause 13.2(a)] — Insert coma ‘,’ after the word ‘cutting’.