

AMENDMENT NO. 1 APRIL 1976

TO

**IS:6049-1971 CODE OF PRACTICE FOR
APPLICATION OF TEMPORARY CORROSION
PREVENTIVES**

Alterations

(Page 3, clause 0.3) - Delete Sl No. 1, 2, 8 and 10 and re-number the remaining serial numbers accordingly.

(Page 6, clauses 3.1 and 3.2) - Delete and re-number the remaining clauses accordingly.

(Pages 10 and 11, clauses 3.8 and 3.10) - Delete and re-number clauses '3.9 and 3.11' as '3.8 and 3.9'.

(CEDC 1)