

AMENDMENT NO. 2 FEBRUARY 2026
TO
IS 17236 : 2019 PREVENTION AND SAFETY AGAINST FIRE IN ROPEWAYS —
CODE OF PRACTICE

[Page 2, clause 8.4, (d)] — Delete.

(Page 3, clause 8.6) — Insert the following at the end:

‘8.7 Lift

Generally, in ropeway installations lift is provided in the open areas. Body of the lift shall be made of fire-resistant materials.

8.8 Maintenance

- a) Periodic cleaning of the installation to avoid accumulation of grease/oil/dust or any combustible material; and
- b) Periodic cleaning of the electrical panels of any accumulated dust, carbon deposit etc. also tightening of all mounting bolts/screws.

8.9 Maintain strict “No Smoking or Open Flames” policy in stations, control rooms, DG room, storage of flammable material etc.’

(Page 3, clause 10.3) — Insert the following at the end:

‘10.4 In Case of Fire

- a) Ropeway operation shall be stopped immediately;
- b) Passengers to be alerted to remain calm via PA system or intercom;
- c) Use of the nearest fire extinguisher shall be considered (base of flames to be aimed);
- d) Local fire service and ropeway emergency team shall be called; and
- e) Passengers shall be evacuated as per emergency procedures (rope or ladder rescue).’

(MED 06)

Price Group 1
Publication, BIS, New Delhi