

**AMENDMENT NO. 2 JANUARY 2011
TO
IS 10096 (PART 2) : 1983 RECOMMENDATIONS FOR INSPECTION, TESTING
AND MAINTENANCE OF RADIAL GATES AND ROPE DRUM HOISTS**

**PART 2 INSPECTION, TESTING AND ASSEMBLY AT THE
TIME OF ERECTION**

(Page 7, clause 2.7.7, line 1) — Substitute 'correct' for 'corrct'.

(WRD 12)

Reprography Unit, BIS, New Delhi, India