

**AMENDMENT NO. 1 FEBRUARY 2017**  
**TO**  
**IS 10096 (PART 3) : 2002 RECOMMENDATIONS FOR**  
**INSPECTION, TESTING AND MAINTENANCE OF**  
**RADIAL GATES AND ROPE DRUM HOISTS**

**PART 3 AFTER ERECTION**

*(Second Revision)*

[Page 1, clause 4.3.1, Sl No. VI) 1), col 2] — Substitute ‘lubricant’ for ‘grease’ .

[Page 1, clause 4.3.1, Sl No. X) 1d), col 2] — Substitute ‘check for its proper function and calibration with actual gate position’ for ‘check for its proper function and rectify’.

[Page 1, clause 4.3.1, Sl No. X) 1) 1e), col 1] — Substitute ‘e) Reduction gear box’ for ‘e) Reduction gear box (worm reducer)’.

[Page 1, clause 4.3.1, Sl No. XI) f), col 1] — Insert the following at the end:

‘g) foundation bolts for brakes and plumber block’

[Page 5, clause 5.5, Sl No. 1) col 2) 1)] — Substitute the following for the existing :

‘1. No supply or phase loss or low voltage (supply)’

[Page 5, clause 5.5, Sl No. 3), col 2) 1)] — Substitute the following for the existing:

‘1. No supply or phase loss’

[(Page 5, clause 6.2 f)] — Substitute ‘lubricated’ for ‘greased’.

[(Page 5, clause 6.2 g)] — Substitute ‘reduction gear box unit’ for ‘worm reduction unit’ .

[(Page 5, clause 6.2 p) 2)] — Substitute ‘Manufacturer recommended lubricant’ for ‘Cardium compound’.