

**AMENDMENT NO. 1 OCTOBER 2009
TO
IS 10234 : 1982 RECOMMENDATIONS FOR GENERAL
PIPELINE WELDING**

(Page 3, Foreword, clause 0.3, fourth line) — Substitute ‘19th edition, September 1999’ for ‘14th edition, January 1977’.

(Page 9, clauses 5.1 and 5.3, heading) — Add the word ‘**Welding**’ before ‘**Procedure**’.

(Page 11, clause 5.3) — Add the following in between (k) and (m):

‘l) Type and removal of line-up clamp.

Internal line-up clamp or external line-up clamp. For external line-up clamp, minimum percent of root bead weld to be completed before removal of the clamp.’

(Page 17, clause 5.3) — Add the following at the end:

‘s) Speed of travel.

The range for speed of travel, in millimetres per minute, shall be specified for each pass.’

[Page 17, clause 5.4(d)] — Substitute the following for the text in the bracket:

‘Pipe axis vertical to horizontal or vice versa; pipe roll to fixed or vice versa’.

(Page 18, clause 5.4) — Add the following items at the end:

‘q) Decrease in specified preheat temperature.

‘r) Addition of post weld heat treatment or a change from the ranges or values specified in the welding procedure’.

(Page 24, clause 6.3.1, heading) — Substitute the words ‘*Buttwelds up to 10 mm*’ for ‘*of any Thickness Buttwelds*’.

(Page 26, clause 7.3, lines 6 and 7) — Substitute the words ‘in combination with downhill technique’ for ‘and conditions make it difficult to prevent movement of the pipe or if the weld will be unduly stressed’.

Amend No. 1 to IS 10234 : 1982

(Page 27, clause 7.4.2, line 1) — Substitute the words ‘pipe facing machine’ for ‘machine tool’.

(Page 27, clause 7.8.2, line 6) — Add the words ‘and where vertical downhill technique is used’ in between the words ‘services’ and ‘to’.

(Page 27, clause 7.8.2.1) — Add the following new clause:

‘7.8.3 Arc strikes on the pipe wall is not permitted. If accidentally strikes occurred such arc strikes shall be repaired using a procedure approved by the purchaser.’

(Page 29, clause 9.2, line 4) — Delete the words ‘strength of the’.

(Page 29, clause 9.3.1, line 5):

- a) Substitute ‘25 mm’ for ‘12 mm’.
- b) Add the word ‘continuous’ before ‘300 mm’.

(Page 30, clause 9.3.3) — Add the following at the end:

‘For the areas that exceed the density of the thinner base material, the criteria prescribed for burn through shall be applied.’

(Page 31, clause 9.3.5) — Add the following at the end:

‘Also, the total length of incomplete fusion due to cold lap shall not exceed 8 percent of the circumference of the pipe.’

(Pages 31 and 32, clauses 9.4.1, 9.4.2, 9.5.1.1, 9.5.1.2, 9.5.2.1 and 9.5.2.2, line 1) — Substitute ‘60’ for ‘50’.

(Page 32, clause 9.6.4) — Add the following at the end:

‘Also the total length of the hollow bead shall not exceed 8 percent of the circumference of the pipe’.

(Page 36, clause 11.1, line 1) — Add the following at the end:

‘The extent of radiographic testing is to be decided by the designer and shall be approved by the purchaser.’

Amend No. 1 to IS 10234 : 1982

(Page 37, Appendix A, second row, under the heading ‘Preheat’) — Insert the following below ‘Interpass Temp.’:

Type of line-up clamp: Internal/External
Removal of line-up clamp:
Time lapse between root and hot pass:min’.

(Page 37, Appendix A, third row, under the heading ‘Post-Weld Heat Treatment’):

- a) Add the word ‘Holding’ before the words ‘Temperature’ and ‘Time’.
- b) Add the following at the end:
‘Heating rate’
‘Cooling rate’

(Page 37, Appendix A, third row, second column) — Add the following under ‘Gas’:

‘Shielding gas flow rate’

(Page 39, Appendix B, line 1) — Substitute the word ‘Standard’ for ‘Welding’.

(Page 43, Appendix D, col 2, heading) — Substitute the word ‘Process’ for ‘Powers’.

(MTD 12)