

AMENDMENT NO. 1 AUGUST 1997
TO
IS 101 (Part 3/Sec 1) : 1986 METHODS OF SAMPLING
AND TEST FOR PAINTS, VARNISHES AND RELATED
PRODUCTS

PART 3 TESTS ON PAINT FILM FORMATION

Section 1 Drying Time

(Third Revision)

(Page 1, clause 2.1, line 1) — Substitute 'silver sand' for 'ballotini'.

(Page 1, clause 3.1, line 1) — Substitute 'Silver Sand' for 'Ballotini' (Small Transparent Glass Spheres)'.

(Page 1, clause 3.1, line 2) — Substitute 'silver sand' for 'ballotini' and wherever it appears subsequently in the standard.

(Page 1, clause 3.1, line 3) — Substitute '150' for '125' and '300' for '250'.

(Page 2, clause 5.3) — Substitute the following for the existing clause:

'5.3 Tack-Free Drying — Painted film on the panel can be tested by either of the two methods given below at 5.3.1 and 5.3.2.

5.3.1 Method A — Place the panel in one pan of a suitable balance and counterpoise it with weights. Place a further weight of 2.25 kg and press on the dried film surface of the panel with the thumb till the two pans are balanced. Hold for one minute and then slowly release. No sign of stickiness to the thumb shall be apparent and the thumb impression, if produced, shall be such as can be wiped away with dry cotton wool.

5.3.2 Method B — Place a 50 mm × 75 mm piece of special test paper on the film and place upon it a steel cylinder 50 mm in diameter and mass of 2.85 kg as to produce 140 g/cm² pressure. At the end of 5 seconds, remove the cylinder and invert the test panel. The film shall be considered tack free when the paper drops of the test film within 10 seconds.

Amend No. 1 to IS 101 (Part 3/Sec 1) : 1986

Note — The test paper shall be K-4 power cable paper and when conditioned in accordance with IS 1060 (Part 1) : 1966 'Methods of sampling and test for paper and allied products: Part 1 (revised)' conforms to the following requirements:

Grammage, g/m ²	150 ± 3.75
Thickness, mm	0.17
Air resistance, S/100 cm ² /6.25 cm ²	350
Coefficient of static friction	0.5
Friction angle, deg	22'

(CHD 020)