

—●— $EE^{75, \Delta\varepsilon = 0.00}, P = 35\text{ W}$ —●— $EE^{75, \Delta\varepsilon = 0.025}, P = 38\text{ W}$ —●— $EE^{75, \Delta\varepsilon = 0.05}, P = 40\text{ W}$
—■— $RM^{35, \Delta\varepsilon = 0.00}, P = 35\text{ W}$ —■— $RM^{75, \Delta\varepsilon = 0.025}, P = 75\text{ W}$ —■— $RM^{75, \Delta\varepsilon = 0.05}, P = 75\text{ W}$

