		Assignment	1 Page 9
2.	1.0	Differentiate between Minimum and Maximum modes of 8086.	
	1]	Minimum mode Here MN/MX is connected to Vec.	Maximum mode Here MN/MX is connected to Ground.
		mode. 8086 is the only processor in the circuit.	It is a multiprocessor inde. Along with 8086. There can be other processors like 8087 and 8089 in the circuit.
		given by 8086.	As there are multiple processors, ALE for the latch is given by 8288. pres controller.
		INTA for interrupt acknowledgement is produced by 8086.	INTA for interrupt : acknowledgement is produced by 8288 Blue Controller.
		The circuit is simples but does not support multiprocessing.	complex but supports.
		Bus request are grant is hondled using HOLD and HLDA signals.	is hardled using RQ/