## Multi-projector tiled display: Instruction Manual

Pranav Kant Gaur, pranav@barc.gov.in

September 22, 2014

## 1 Introduction

This document describes the instructions for correctly running the Multi-projector geometric alignment and edge blending modules. Please note that this document is only a HOWTO and hence does not detail any explaination regarding why any particular step has been performed. Running multiprojector display calibration has 6 steps:

- 1. Startup the rendering cluster.
- 2. Position the camera in front of projection screen for computing camerato-screen homography.
- 3. Run camera-screen homography estimation routine.
- 4. Run geometric alignment module.
- 5. Run edge-blending module.
- 6. Applying newly calculated calibration settings.

## 2 Addendum

Screencast running\_calibration.ogv shows the calibration process, whereas screencast applying\_settings.ogv shows how to apply the newly calculated settings. In addition to the screencasts of the calibration process:

- Press key 'y'(case-sensitive) to capture image on Camera\_view window.
- While running ./feature\_projection.sh, press key 'n'(case-sensitive)(on its program window) to project checkerboard on the next projector.
- Press **'ESC'** key to stop execution of **./feature\_projection.sh**(on its program window).