DRINKPRIME WATERWALA LABS PVT LTD

TITLE: FINAL TESTING PROCESS

1. MATERIAL REQUIRED:

S.NO.	ITEM NAME	UOM	QTY.
1	Device	Nos	1
2	Accessory pouch	Nos	1
3	Power adaptor 2A	Nos	1
4	Back panel assembling Screws	Nos	5

2. TOOLS REQUIRED:

S.NO.	ITEM NAME	UOM	QTY.
1	Ball Valve	Nos	1
2	Air regulator and pressure Gauge	Nos	1

3. ACTIVITIES:

1. Ensure that the sponsor code and PID (Process Identification) are correctly mapped in the DP assembly app.

2. Record the materials used for the refurbishment process in the system.

3. Perform an air leak test by applying an input air pressure of 45 PSI. Spray Colin at to detect any leaks in the elbow assembly.

4. Inspect other parts and connections thoroughly for any signs of leakage. Hold at this pressure for 15 min and observe the components and tubing at joints. There shall not be any leakage water bubbles (Sprayed Colin) or hissing noise when the pressurization is held for 15 min. Release the pressure by opening the open/close valve and turn off the pressurization pump.

5. After completing the air leak test, verify the functionality of the Float cut off/cut in and adaptor.

6. After final testing, the float sensor needs to be secured with filament tape inside the tank lid in its original position.

7. Clean & pack the devices.

PREPARED BY	REVIEWED BY	APPROVED BY	ISSUED BY

4. **SAFETY INSTRUCTIONS:** Keep the material away from the gang way.

5. **CHECKS:** Ensure that the back cover and Front facia are aesthetically ok.

6. **RESPONSIBILITY:** Operator & Line QC person.