DRINKPRIME WATERWALA LABS PVT LTD

REFERENCE: 0024DPCRO007	REVISION: R0	DATE: 11-04-2024	Page 1 of 1
TITLE: W.I. FOR 7th STAGE			

TITLE: DEVICE PACKING.

1. MATERIAL REQUIRED:

S.NO.	ITEM NAME	UOM	QTY.
1	Back Panel	Nos	1
2.	Filament Tape	Mtr	0.5
3.	BOPP Tape 3" with DP Logo	Mtr	1
4.	BOPP TAPE 1" TRANSPARENT	Mtr	0.5

2. Tools Required

S.NO.	ITEM NAME	UOM	QTY.
1	Tape Gun	Nos	1
2	Microfiber cloth	Nos	1
3	Permanent Marker	Nos	1
4	CIF Cream	Nos	1

3. ACTIVITIES:

1. Verify accessories and adaptors; mark with a tick to indicate verification.
2. Assemble the back panel onto the device using filament tape.
3. Clean the device using a microfiber cloth and CIF polishing cream for a polished finish.
4. Conduct a final visual inspection to ensure quality standards are met.
5. Complete the packing process for shipment or storage.

4. **SCRAP DISPOSAL:** Put the scrap in the respective bins only.
5. **SAFETY INSTRUCTIONS:** Keep the material away from the gang way.
6. **RESPONSIBILITY:** Operator

7. QC CHECKS:

1. Ensure that the box should not open when we handle the box.
2. Ensure that the serial no. written, and the bar code should be of the same no.

PREPARED BY	REVIEWED BY	APPROVED BY	ISSUED BY