

Ticket Report

Generated: 02-23-2026 14:07

Filters: {'date_from': "", 'date_to': "", 'direction': "", 'job_id': "", 'material_id': ""}

Tickets

DT-2026-000004 | 02-19-2026 - 13:59 | IN | Topsoil | 5.0 yd
DT-2026-000003 | 02-19-2026 - 13:49 | IN | Topsoil | 11.0 yd
DT-2026-000002 | 02-19-2026 - 13:46 | IN | Topsoil | 11.0 yd
DT-2026-000001 | 02-19-2026 - 13:19 | IN | Topsoil | 12.0 yd
DT-2026-000009 | 02-23-2026 - 13:38 | AECOM | OUT | Topsoil | 2.0 load
DT-2026-000006 | 02-19-2026 - 14:43 | Cleveland Construction, Inc. | IN | Topsoil | 8.0 yd
DT-2026-000010 | 02-23-2026 - 13:41 | Evergreen Construction Company | IN | Topsoil | 2.0 load
DT-2026-000008 | 02-23-2026 - 13:36 | Greenspace Construction Servic | IN | Topsoil | 2.0 load
DT-2026-000005 | 02-19-2026 - 14:32 | Marous Bros. Construction | IN | Topsoil | 6.0 yd
DT-2026-000007 | 02-19-2026 - 15:05 | Woda Cooper Companies Inc. | IN | Topsoil | 5.0 yd

Totals By Unit

load : 6.0

yd : 58.0

Totals By Material

Topsoil (load) : 6.0

Topsoil (yd) : 58.0