

Packing AI Report

Container: 10.0 x 5.0 x 5.0

Utilization: 81.60 %

Box box-1: pos=(0.0,0.0,0.0), size=(10.0,2.0,5.0), caution=fragile

Box box-5: pos=(0.0,0.0,2.0), size=(7.0,2.0,3.0), caution=none

Box box-5: pos=(0.0,3.0,2.0), size=(7.0,3.0,2.0), caution=none

Box box-3: pos=(7.0,0.0,2.0), size=(2.0,2.0,5.0), caution=waste