Apex Rapid HVAC LLC

88 Bluxome St, Unit 4
San Francisco, CA 94107
(415) 555-0191 · ap@apexrapidhvac.example
CA Lic. #SAMPLE-4410 (C-20)

INVOICE

INVOICE NO.	**APX-0091**
INVOICE DATE	10/16/2026
TERMS	Net 15
DUE DATE	**10/31/2026**
WORK ORDER	SVC-0091

BILL TO
Lintel Property Holdings LLC
Attn: Accounts Payable
PO Box 7741
Oakland, CA 94604-7741

SERVICE ADDRESS (JOB SITE)
410 Townsend St, San Francisco, CA 94107
Date of service: 10/15/2026
Technician: R. Mendez

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
Emergency after-hours dispatch	1 ea	450.00	450.00
HVAC technician labor	6 hr	225.00	1,350.00
Condenser fan motor, 1/2 HP (OEM)	1 ea	1,180.00	1,180.00
Run capacitor, 45/5 MFD	2 ea	85.00	170.00
Refrigerant R-410A recharge	1 ea	300.00	300.00

WORK PERFORMED

At 410 Townsend St, San Francisco, CA 94107: After-hours call: rooftop unit RTU-2 not cooling. Replaced condenser fan motor and run capacitors, recharged refrigerant, tested.

PAYMENT

Please reference invoice APX-0091 with your payment. ACH or check accepted. A 1.5% monthly finance charge applies to balances past due.

Subtotal	3,450.00
Sales tax (labor and services, not taxable)	0.00
Total due	**$3,450.00**

Thank you for your business.

SAMPLE BILL FOR SOFTWARE TESTING. Fictional document generated for the Lintel demo; not issued by the named company. No money moves.