SYNTHETIC — not a real-world measurement

PartSmith repair card

Battery compartment cover

Family: cover

VERIFIED

Max error: 0.25 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.991, Hausdorff 0.25 mm, mean 0.08 mm
Part tests: 10/10 passed
- top: refined in the photo frame by -0.03 deg, (-0.02, -0.02) mm on the mat
- Verified: all 8 P0 tests pass and every measured view is within tolerance.
- top view (photo frame): IoU 0.991 (needs >= 0.97), Hausdorff 0.25 mm (needs <= 0.5 mm)

Key dimensions

Length: 45.15 mm ± 0.22 [measured]
Width: 29.82 mm ± 0.22 [measured]
Thickness: 1.50 mm ± 0.30 [user stated]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Y: -Y side on the bed

Repair passport

XKDAH1

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/XKDAH1

Or type the id on the PartSmith site at /p/<id>. No new photos needed.