PartSmith repair card

Custom part (not a battery compartment cover: its

Family: custom

BEST EFFORT

Max error: 0.15 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.998, Hausdorff 0.15 mm, mean 0.04 mm
Part tests: 10/12 passed
- top: refined in the photo frame by -0.00 deg, (-0.03, +0.03) mm on the mat
- top view (photo frame): IoU 0.998 (needs >= 0.97), Hausdorff 0.15 mm (needs <= 0.5 mm)
- Test failed: thinnest wall >= 0.8 mm (FDM) (model: 0.76).

Key dimensions

Length: 85.69 mm ± 0.13 [measured]
Width: 54.08 mm ± 0.12 [measured]
Thickness: 0.76 mm ± 0.30 [user stated]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: no
Orientation: -Z: mounting face (Z=0) on the bed, as modelled