PartSmith repair card

Replacement part

Family: clip

BEST EFFORT

Max error: 1.32 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.991, Hausdorff 0.53 mm, mean 0.05 mm
side: IoU 0.952, Hausdorff 1.32 mm, mean 0.15 mm
Part tests: 14/14 passed
- top: refined in the photo frame by +0.17 deg, (+0.05, -0.04) mm on the mat
- side: refined in the photo frame by -0.00 deg, (-0.47, +0.29) mm on the mat
- top view (photo frame): IoU 0.991 (not gated), mean contour distance 0.05 mm (needs <= 0.15 mm), Hausd

Key dimensions

Length: 43.88 mm ± 0.10 [measured]
Width: 18.10 mm ± 0.10 [measured]
Thickness: 3.00 mm ± 0.30 [user stated]
hole_1 Ø: 3.55 mm ± 0.06 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: no
Orientation: -Z: mounting face (Z=0) on the bed, as modelled