SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

Battery compartment cover

Family: cover

BEST EFFORT

Max error: 1.16 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.993, Hausdorff 0.46 mm, mean 0.07 mm
side: IoU 0.807, Hausdorff 1.16 mm, mean 0.17 mm
Part tests: 11/11 passed
- top: refined in the photo frame by -0.06 deg, (+0.03, -0.03) mm on the mat
- side: refined in the photo frame by +0.15 deg, (+0.06, +0.04) mm on the mat
- top view (photo frame): IoU 0.993 (needs >= 0.97), Hausdorff 0.46 mm (needs <= 0.5 mm)

Key dimensions

Length: 53.54 mm ± 0.10 [measured]
Width: 33.67 mm ± 0.08 [measured]
Thickness: 1.50 mm ± 0.30 [user stated]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: no
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

T5EBA5

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/T5EBA5

Or type the id on the PartSmith site at /p/<id>. No new photos needed.