SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

Battery compartment cover

Family: cover

BEST EFFORT

Max error: 3.00 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.962, Hausdorff 1.99 mm, mean 0.41 mm
side: IoU 0.456, Hausdorff 3.00 mm, mean 0.96 mm
Part tests: 9/11 passed
- top: refined in the photo frame by +0.08 deg, (-0.27, +0.76) mm on the mat
- side: refined in the photo frame by -2.96 deg, (+2.55, +2.24) mm on the mat
- top view (photo frame): IoU 0.962 (needs >= 0.97), Hausdorff 1.99 mm (needs <= 0.5 mm) (worst at x=26.0,

Key dimensions

Length: 51.49 mm ± 0.09 [measured]
Width: 37.94 mm ± 0.08 [measured]
Thickness: 1.50 mm ± 0.30 [user stated]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Y: -Y side on the bed

Repair passport

Q8535R

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/Q8535R

Or type the id on the PartSmith site at /p/<id>. No new photos needed.