SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

Annular spacer

Family: spacer

VERIFIED

Max error: 0.08 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.983, Hausdorff 0.05 mm, mean 0.02 mm
side: IoU 0.981, Hausdorff 0.08 mm, mean 0.03 mm
Part tests: 14/14 passed
- top: refined in the photo frame by +0.33 deg, (+0.01, +0.01) mm on the mat
- side: refined in the photo frame by -0.12 deg, (-0.02, -0.00) mm on the mat
- Verified: all 10 P0 tests pass and every measured view is within tolerance.

Key dimensions

Length: 7.98 mm ± 0.06 [measured]
Width: 7.96 mm ± 0.06 [measured]
Thickness: 8.50 mm ± 0.30 [user stated]
hole_1 Ø: 3.95 mm ± 0.04 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

1J877Z

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/1J877Z

Or type the id on the PartSmith site at /p/<id>. No new photos needed.