PartSmith repair card

Wall hook

Family: hook

BEST EFFORT

Max error: 4.70 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.947, Hausdorff 1.83 mm, mean 0.38 mm
side: IoU 0.875, Hausdorff 4.70 mm, mean 0.38 mm
Part tests: 16/17 passed
- top: refined in the photo frame by -0.15 deg, (-3.93, -2.12) mm on the mat
- side: refined in the photo frame by -0.07 deg, (+0.22, +0.34) mm on the mat
- top view (photo frame): IoU 0.947 (needs >= 0.97), Hausdorff 1.83 mm (needs <= 0.5 mm) (worst at x=-20.0

Key dimensions

Length: 49.83 mm ± 0.12 [measured]
Width: 22.27 mm ± 0.12 [measured]
Thickness: 4.50 mm ± 0.30 [user stated]
hole_1 Ø: 3.91 mm ± 0.04 [measured]
hole_2 Ø: 3.90 mm ± 0.04 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

KG12DT

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/KG12DT

Or type the id on the PartSmith site at /p/<id>. No new photos needed.