SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

Battery compartment cover

Family: cover

BEST EFFORT

Max error: 1.11 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.975, Hausdorff 1.11 mm, mean 0.28 mm
side: IoU 0.953, Hausdorff 1.09 mm, mean 0.12 mm
Part tests: 8/11 passed
- top: refined in the photo frame by +0.16 deg, (-0.90, -0.85) mm on the mat
- side: refined in the photo frame by -0.41 deg, (+2.86, +7.03) mm on the mat
- top view (photo frame): IoU 0.975 (needs >= 0.97), Hausdorff 1.11 mm (needs <= 0.5 mm) (worst at x=-25.7

Key dimensions

Length: 52.66 mm ± 0.10 [measured]
Width: 30.40 mm ± 0.09 [measured]
Thickness: 2.00 mm ± 0.30 [user stated]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

Q1QD5K

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/Q1QD5K

Or type the id on the PartSmith site at /p/<id>. No new photos needed.