SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

Battery compartment cover

Family: cover

VERIFIED

Max error: 0.39 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.987, Hausdorff 0.39 mm, mean 0.12 mm
Part tests: 10/10 passed
- top: refined in the photo frame by +0.06 deg, (-0.08, -0.17) mm on the mat
- Verified: all 8 P0 tests pass and every measured view is within tolerance.
- top view (photo frame): IoU 0.987 (needs >= 0.97), Hausdorff 0.39 mm (needs <= 0.5 mm)

Key dimensions

Length: 45.41 mm ± 0.12 [measured]
Width: 30.03 mm ± 0.11 [measured]
Thickness: 1.50 mm ± 0.30 [user stated]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

WMRMP2

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/WMRMP2

Or type the id on the PartSmith site at /p/<id>. No new photos needed.