SYNTHETIC · MIXED MODELS — not a real-world measurement

PartSmith repair card

Replacement part

Family: hook

VERIFIED

Max error: 0.43 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.988, Hausdorff 0.43 mm, mean 0.10 mm
side: IoU 0.983, Hausdorff 0.40 mm, mean 0.05 mm
Part tests: 12/14 passed
- top: refined in the photo frame by +0.00 deg, (+0.01, -0.01) mm on the mat
- side: refined in the photo frame by -0.04 deg, (+0.11, +0.13) mm on the mat
- Verified: all 9 P0 tests pass and every measured view is within tolerance.

Key dimensions

Length: 66.53 mm ± 0.13 [measured]
Width: 19.43 mm ± 0.12 [measured]
Thickness: 3.00 mm ± 0.30 [user stated]
hole_1 Ø: 4.09 mm ± 0.04 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

9102AQ

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/9102AQ

Or type the id on the PartSmith site at /p/<id>. No new photos needed.