PartSmith repair card

Cupboard turn-button latch

Family: latch

BEST EFFORT

Max error: 0.76 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.992, Hausdorff 0.19 mm, mean 0.04 mm
side: IoU 0.959, Hausdorff 0.76 mm, mean 0.16 mm
Part tests: 14/14 passed
- top: refined in the photo frame by -0.03 deg, (+0.06, -0.05) mm on the mat
- side: refined in the photo frame by -0.20 deg, (-0.26, -0.18) mm on the mat
- top view (photo frame): IoU 0.992 (not gated), mean contour distance 0.04 mm (needs <= 0.15 mm), Hausd

Key dimensions

Length: 55.08 mm ± 0.09 [measured]
Width: 15.96 mm ± 0.08 [measured]
Thickness: 7.50 mm ± 0.30 [user stated]
hole_1 Ø: 3.81 mm ± 0.05 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: +Z: upside down (top face on the bed)

Repair passport

GDZVKF

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/GDZVKF

Or type the id on the PartSmith site at /p/<id>. No new photos needed.